


HARTZELL

PROPELLER LOGBOOK



PROPELLER MODEL HC-I3Y1R-IN



PROPELLER S/N NY219 B

LOGBOOK # 1

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
<h2 style="text-align: center;">Propeller Log</h2>			
Date: <u>8-20-2014</u>	Hobbs Time: <u>3.7</u>		
Aircraft S/N: <u>4636638</u>	Reg. Number: <u>N4428V</u>		
Prop Model: <u>HC-I3Y1R-1N</u>	S/N: <u>NY219B</u>		
Complied with Hartzell Propeller Owner's Manual <u>145. 6-7 THRU 6-12</u> Performed Lubrication of Prop by Manufacturer during Flight Testing with Aeroshell #6 after 1 to 2 hours operation.			
Signature: <u>[Signature]</u> Name: <u>Tony Schweitzer</u> A&P Certificate Number: <u>AP3328631</u>			
 PIPER AIRCRAFT, INC.			

LUBBOCK AERO 6304 N. Cedar Ave., Lubbock, TX 79403 Date: Dec. 22, 2015 N#: 920C Make: Hartzell Model: HC-I3Y1R-1N S/N: NY219B Hobbs: 163.7 PTT: 163.7 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition. <u>[Signature]</u> Gene Seitz AP2148062IA			
LUBBOCK AERO 6304 N. Cedar Ave., Lubbock, TX 79403 Date: Jan. 4, 2017 N#: 920C Make: Hartzell Model: HC-I3Y1R-1N S/N: NY219B Hobbs: 304.1 PTT: 304.1 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition. <u>[Signature]</u> Chad R. Burns AP2829180IA			

Date	Pro TSN
	<p>6304 N. Cedar Ave., Lubbock, TX 79403 Date: Feb. 2, 2018 N#: 920C Make: Hartzell Model: HC-I3Y1R-IN S/N: NY219B Hobbs: 436.0 PTT: 436.0 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition.  Chad R. Burns AP2829180IA</p>
	<p>LUBBOCK AERO</p> <p>6304 N. Cedar Ave., Lubbock, TX 79403 Date: March 6, 2019 N#: 920C Make: Hartzell Model: HC-I3Y1R-IN S/N: NY219B Hobbs: 537.5 PTT: 537.5 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W 500 hour Hartzell propeller composite blade coin-tap inspection, as per blade manual no. 135. No defects found. Next due: PTT: 1037.5 C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition.  Daniel S. Mayo AP3817553IA</p>

	<p>LUBBOCK AERO</p> <p>6304 N. Cedar Ave., Lubbock, TX 79403 Date: Apr 10, 2020 N#: 920C Make: Hartzell Model: HC-I3Y1R-IN S/N: NY219B Hobbs: 660.8 PTT: 660.8 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition.  Chad R. Burns AP2829180IA</p>
	<p>LUBBOCK AERO</p> <p>6304 N. Cedar Ave., Lubbock, TX 79403 Date: May 10, 2021 N#: 920C Make: Hartzell Model: HC-I3Y1R-IN S/N: NY219B Hobbs: 758.1 PTT: 758.1 C/W propeller 100-hour inspection IAW FAR 43 appendix D. C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease. No AD's due at this time. I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition.  Monty Conn AP4189614IA</p>

304 N. Cedar Ave., Lubbock, TX 79403

Date _____

Date: June 1, 2022

N#: 920C

Make: Hartzell

Model: HC-13Y1R-1N

S/N: NY219B

Hobbs: 836.5

PTT: 836.5



C/W propeller 100-hour inspection IAW FAR 43 appendix D.

C/W prop deice boot inspection. --Lubed hub with Aeroshell #6 grease.

No AD's due at this time.

I certify that this propeller has been inspected IAW a 100 hour / annual inspection and was determined to be in airworthy condition.

Monty Conn AP41896141A

 Lore Aviation Services LLC Propeller		Date: 8/18/2023		
		500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496		
N920C	Hobbs: 857.5	Tach:	TSMO:	TT: 857.5
Performed Annual inspection IAW with 14 CFR Part 43 App. D and Hartzell inspection checklist. Performed engine ground run and op's check. Indexed and removed spinner. Inspected propeller mounting hardware for proper installation and blades for damage. Reinstalled spinner. Ground run indicated minimal vibrations. Researched and verified AD's				
I certify that this propeller has been inspected IAW an Annual Inspection and was determined to be in airworthy condition. _____ END _____				
 Christopher Lore A&P 3458101 IA				